

VOLUME No. 2
1953-56 SERIES



service bulletins

These Blue Streak Service Bulletins have been written with one thing in mind — to make better mechanics. Read them! Study them! They'll make you a better informed, more efficient mechanic. They've done it for thousands of other successful registered Blue Streak dealers. The helpful clues and service tips in these bulletins will enable you, too to join the ranks of the "Sherlock McKanics" —those No. 1 trouble shooters—America's ace mechanics.



STANDARD MOTOR



PRODUCTS, INC.

INDEX

INDEX BY SUBJECT

	Bulletin No.	Page		Bulletin No.	Page
Allen E-309 coil tester	88-56	93	Rotors, Ford, elimination of breakage	74-53	69
Ammeters, installation on cars with "No Charge" lights	84-55	85	"No Charge", light, function, operation of	80-54	79
Breaker Arms, damage by defective cams	72-53	65	Voltage Regulators, general hints	85-55	87
Breaker Arms, Excessive bumper block wear	76-54	72	Voltage Regulators, look before condemning or replacing	81-55	81
Coils, testing on the Allen #1403	82-55	82	Voltage Regulators, servicing, misconceptions	77-54	74
Distributor, External adjustment	86-55	89	Voltage Regulator, servicing and tailoring the setting	78-54	76
Distributor, Chevrolet, 1953 and later	75-53	70	Battery, 12-volt	83-55	83
Distributor head, peculiar trouble	79-54	78	Electrical system, 12 volts and why	73-53	67
Ignition System, 12 volts	87-56	91			

INDEX BY BULLETIN NUMBER

Bulletin No.	Page	Bulletin No.	Page
72-53	65-66	81-55	81
73-53	67-68	82-55	82
74-53	69	83-55	83-84
75-53	70-71	84-55	85-86
76-54	72-73	85-55	87-88
77-54	74-75	86-55	89-90
78-54	76-77	87-56	91-92
79-54	78	88-56	93
80-54	79-80		